

# General Environmental Incident Summary

**Incident:** 4079      **Date/Time Notice:** 5/2/2016      10:00A      **DEM Incident No:**  
**Responsible Party:** Sterling Construction Management, LLC  
**Date Incident:** 4/30/2016      **Time Incident:** 1200      **Duration:** 5 minutes  
**County:** Dunn      **Twp:** 147      **Rng:** 97      **Sec:** 12      **Qtr:**

**Lat:** 47.56259      **Long:** -102.97990      **Method:** Navigation quality GPS

**Location Description:** ONEOK Bear Creek NGL Pipeline construction ROW (currently under construction). From intersection of 115th Ave NW / 10th Street NW travel approximately 0.75 miles east on 10th Street NW. Turn north on well pad access road. ONEOK Bear Creek NGL pipeline corridor crosses well pad access road approximately 0.25 miles north of 10th Street NW.

**Submitted By:** Todd Kelvington      **Affiliation:** ONEOK

**Address:** 100 West 5th Street

**City:** Tulsa      **State:** OK      **Zip:**

## Received By:

**Contact Person:** Chuck Delp  
3158 Baron Lane Unit East  
Rifle , CO 81650

**Distance Nearest Occupied Building:** 1500 Feet      **Release Contained:** Yes

**Type of Incident:** Construction equipment

**Description of Released Contaminant:** Diesel fuel

**Volume Spilled:** 2.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

## Cause of Incident:

Surface staining from unknown construction source observed along the pipeline ROW. Appears to have originated from a piece of passing equipment or a portable fuel tank.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Not likely. No impact to surface waters. Volume minimal and appears isolated to surface soils which were excavated and removed.

## Action Taken or Planned:

Contractor spill response responded to the stain area and applied spill kits. Approximately 24 gallons of impacted soil were excavated, bagged, and taken to contractor's yard for disposal.

Based upon volume and clean-up action. No additional follow up lab testing is anticipated. Soils will be excavated further during pipeline installation and final ROW reclamation activities.

**Wastes Disposal Location:** Impacted materials from the project are being stored at the contractors yard and will be hauled in bulk at various stages to an approved disposal facility.

**Agencies Involved:**

### **Updates**

---

**Date:** 5/2/2016    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

According to the report, 2 gallons of diesel fuel were released onto pipeline right-of-way. More follow-up needed.

---

**Date:** 5/11/2016    **Status:** No Further Action Requested

**Author:** Kannenberg, Derek

**Updated Volume:**

**Notes:**

On site: 1648

Weather: Cool. Wind and temp not noted.

Site has been remediated. Removed soil has been bagged and, in some cases, disposed of. The site is clean and neat, and appears to be well managed. Requested photos of spills in the future. No further action required.